

VIN: WPOAB29942S685820

Vehicle Model Type: 996 TURBO 6 SPEED MANUAL 4 WHEEL DRIVE

Vehicle Model Year: 2002

Production Plant: Stuttgart

Number of Modules with Faults:2

DME Information

M numbers

032 058 059 130 139 152 197 218 242 265 266 270 273 274 288 335 339 340 410 425
434 437 438 441 446 454 465 476 480 484 498 513 535 537 553 562 563 566 567 571
573 581 586 601 602 620 650 651 657 659 660 661 662 664 680 685 692 912 936 981
98306Y 0AT 0GA 0PS 10MN 11XC 13XM 164M 173W 18K8 1APU 1CJK 6VD 77L 83Y 8D5
9Q1 A4W ABV AWP B2G B9Q BRJ CWM DHT DSS E32 E6I F2L FGU FO4 FV1 GB9 GUM H5L
HU6 JTL KPQ KSA KVD LGB NQ6 PW4 R7L RDU RL0 RTV SK4 TRA UW7 WD1 WQ1 WTU
YB1

Exclusive numbers

XJ4 XKL XMP XMZ XNG XNN XNU XN3 XPA XV1 X97 X98

Z numbers

501 9991

Country coding

, c2

Ignition Ranges

Number of ignitions in range 1 : 24740 Number of ignitions in range 2 : 127

Operating hours counter

1757.1 hours

DME M5201

PART NUMBER(S): 99661868006

1 Fault(s) Present

P1601 CAN timeout instrument cluster

TIPTRONIC

Module not fitted or not communicating

ABS

Module not fitted or not communicating

INSTRUMENT CLUSTER

Module not fitted or not communicating

AIR CONDITIONING

Module not fitted or not communicating

PARK ASSISTANT

Module not fitted or not communicating

SEAT MEMORY

Module not fitted or not communicating

ALARM SYSTEM I48

PART NUMBER(S): 99661826203

1 Fault(s) Present

60 Central locking limit position Lock not reached

AIRBAG

Module not fitted or not communicating

CONVERTIBLE/ TARGA TOP

Module not fitted or not communicating

ROLL-OVER PROTECTION

Module not fitted or not communicating

HBA

Module not fitted or not communicating

Diagnostic Report compiled by Autologic Diagnostics

www.autologic-diagnostics.com